

TO: Jerry Samson

CC: Jerry Rogers

John Hughes  
Wally Rhines

FM: Karl Guttag

RE: VDP Spec

I have looked at the new VDP DATA manual and find the connection specification for the VDP to DRAM as terrible as ever (since nothing has been done). The attitude taken by marketing on this issue is irresponsible to say the least. I have personally dealt with too many customers that have not gotten their systems to work without help simply due to the spec. problem in this area.

The spec must clearly indicate how to connect the VDP to the DRAMs. While an application note appended to the spec will help we must clearly indicate how to connect the DRAM's in the main body of the spec.

The reason for the confusion  
is the very unnatural way the  
~~VDP~~ connects ~~to~~ to the  
DRAMs to the 9900 industry non-standard  
connects.

My proposal is ~~to~~ in two parts, the  
first part is the minimum we must  
do and the second is what we  
should do: ~~use~~ <sup>use</sup> (see appended table)

1) We must include a table<sup>1</sup>  
in the data manual on the pinout  
page that clearly indicates how  
to connect the VDP's AD pins to  
the memories Address pins. I  
suggest we include an errata  
page with all current ~~data~~  
data manuals until the manual  
is fixed.

2) We should give an alternate  
pinout numbering for the VDP's  
pins that conforms to industry  
standard numbering for Dynamic  
RAMS

I have deliberately worded this memo strongly since I have ~~constantly~~  
~~and~~ repeatedly tried to get marketing to remedy this problem and they have consistently indicated that ~~it was the user's problem.~~

In future I will be responsive <sup>and RTGs real</sup> to customers having technical problems with the UDP but I will refer all questions of pinout to marketing since it is their problem.

Regards

Karl Gettay